
Observations on the 10.2.0.B firmware for the Technicolor TG582n router.


<u>Home Network Interfaces</u>: (firmware incompatible with hardware?)

WPS is disabled after installing the new 10.2.0.B firmware:



System Configuration: (minor formatting error)


Date: dashes that should separate dd-mm-yy are displayed after the Date fields. **Time**: colons that should separate hh:mm:ss are displayed after the Time fields.



Intrusion Detection: (minor formatting issue)

Spacing between each listed item has increased compared to previous firmware versions. The way the old firmware displayed this information was better.

This information used to fit on one page but now it spans four pages.



Event Logging: (minor formatting issue)

Spacing between each listed item has increased compared to previous firmware versions (same issue as for the Intrusion Detection screen).

